

# SPEED-LOC™ ADAPTER CHART

MAKE & MODEL	SHANK DEGREE	BOLT SIZE	HOLE CENTER	200 SERIES				410 SERIES			
				200-QCA-4700	200-QCA-4710	200-QCA-5000	200-QCA-5010	100-WDG-0700	410-QCA-5000	410-QCA-5010	410-QCA-5080
<b>AFM</b>											
180, 200, 250, 880	43°	7/16	1-3/4	■	■						
150, 2300, 310, 300	50°	1/2	2-1/4			■		■			
350 SCARICHESEL	50°	1/2	2-1/4			■		■			
<b>ANDERSON</b>											
FIELD CULTIVATORS	47°	3/8	1-3/4		■						
CHISEL PLOWS	50°	1/2	2-1/4			■		■			
<b>BOURGALT</b>											
FIELD CULTIVATORS 6200, 6800, 8800, 8810, 8910	47°	1/2	1-3/4	■							
SPS 270, 360	50°	1/2	2-1/4					■			
5710, 5810 AIR DRILL	47°	1/2	1-3/4	■							
CHISEL PLOWS 9200, 9400, 9500, 9800	50°	1/2	2-1/4			■		■			
3310, 3320 EDGE-ON	(NO ADAPTER FOR THIS APPLICATION)										
<b>BRADY</b>											
FIELD CULTIVATORS	43°	3/8	1-5/8	(NO ADAPTER FOR THIS APPLICATION)							
CHISEL PLOWS	50°	7/16	2-1/4			■		■			
<b>BRILLION</b>											
HFCT MO	47°	7/16	1-5/8	■							
<b>BUSH HOG</b>											
FIELD CULTIVATORS	47°	3/8	1-3/4		■						
CHISEL PLOWS	50°	7/16	2-1/4			■		■			
<b>CASE</b>											
FC, FCW, FCM, 10, 50, 55, 645	47°	3/8	1-3/4		■						
4700, 4900, 5000, 645	43°	1/2	2-1/4			■	■	■			■
<b>CASE IH</b>											
255 TIGER-MATE II	47°	7/16	1-3/4		■						
45, 4300, 4500, 4600, 4700, 4800, 4900	47°	7/16	1-3/4		■						
VIBRASHANK	47°	7/16	1-3/4		■						
VIBRACHISEL 5600, 5700	43°	1/2	2-1/4			■	■	■			■
5800, 5850, 5900	50°	1/2	2-1/4			■		■			■
PTX 300, PTX 600	50°	1/2	2-1/4			■		■			■
ATX AIR DRILL WITH EDGE-ON 84° SHANK	(NO ADAPTER FOR THIS APPLICATION)										
ATX 400, 700 AIR HOE DRILL 350 LB OR 550 LB TRIP	50°	1/2	2-1/4			■		■			
<b>CONCORD</b>											
C-SHANKS	50°	1/2	2-1/4			■		■			
EDGE-ON SHANKS	(NO ADAPTER FOR THIS APPLICATION)										
<b>CCIL</b>											
202, 179, 279, 379	47°	3/8	1-3/4		■						
203, 204, 205	43°	1/2	2-1/2					■			■
806, 807, 808	43°	1/2	2-1/2					■			■
CHISEL PLOW (THICK SHANK)	50°	7/16	2-1/4			■		■			
<b>CNH (DMI)</b>											
FIELD CULTIVATORS	47°	7/16	1-3/4		■						
<b>DEGELMAN</b>											
FIELD CULTIVATORS 500	47°	7/16	1-3/4		■						
3000-2	50°	7/16	2-1/4			■		■			
<b>DEMSTER</b>											
CHISEL PLOWS	54°	7/16	2-1/4	(NO ADAPTER FOR THIS APPLICATION)							
<b>EDWARDS</b>											
CHISEL PLOWS	50°	7/16	2-1/4			■		■			
<b>FORWARD</b>											
BOURGALT TYNE 280, 2700, 2800, 8800	47°	1/2	1-3/4	■							
FUSION DELTA	47°	1/2	1-3/4		■						
3000 & 400 SERIES C/P	50°	1/2	2-1/4			■		■			

MAKE & MODEL	SHANK DEGREE	BOLT SIZE	HOLE CENTER	200 SERIES				410 SERIES			
				200-QCA-4700	200-QCA-4710	200-QCA-5000	100-WDG-0700	410-QCA-5000	410-QCA-5010	410-QCA-5080	400-WDG-0300
<b>EZEE-ON</b>											
FIELD CULTIVATORS 3500, 3550, 5550	47°	1/2	1-3/4	■							
6000 WITH FIELD CULTIVATOR SHANK OPTION	47°	1/2	1-3/4	■							
6000 WITH CHISEL PLOW SHANK OPTION	50°	1/2	2-1/4			■			■		
ALL CHISEL PLOWS INCLUDING 7450	50°	1/2	2-1/4			■			■		
7560, 7550	47°	1/2	1-3/4	■							
<b>FLEXI-COIL</b>											
200, 400, 800	47°	7/16	1-3/4		■						
300, 340, 600	50°	1/2	2-1/4			■			■		
820 & ST820 WITH 350 LB & 550 LB TRIPS	47°	1/2	1-3/4		■						
820 & ST820 WITH 550 LB & 650 LB TRIPS	50°	1/2	2-1/4			■			■		
5000 & 7500 DEPENDING ON SHANK OPTION	47°	1/2	1-3/4		■						
5000 & 7500 DEPENDING ON SHANK OPTION	50°	1/2	2-1/4			■			■		
<b>EDGE-ON</b> (NO ADAPTER FOR THIS APPLICATION)											
5000HD & 5500 AIR HOE DRILL 350 LB OR 550 LB TRIP	50°	1/2	2-1/4			■			■		
<b>FRIGGSTAD</b>											
FIELD CULTIVATORS	47°	7/16	1-3/4		■						
CHISEL PLOWS (OLDER MODELS)	50°	7/16	2-1/4			■			■		
CHISEL PLOWS	50°	1/2	2-1/4			■			■		
<b>GASON</b>											
5100 SERIES	46°	7/16	1-3/4	■							
SCARITILL & EH SCARITILL	47°	1/2	BOTH		■						
7100 ECOTILL	50°	1/2	2-1/4			■			■		
<b>GESSNER</b>											
HR 1200	50°	1/2	2-1/4			■			■		
<b>GLENCOE</b>											
PC, MPC, PCMW	47°	3/8	1-3/4		■						
CHISEL PLOWS	47°	7/16	2-1/4			■			■		■
HIGH CLEARANCE	50°	7/16	1-2/4			■			■		
<b>GRAHAM</b>											
CHISEL PLOWS	50°	1/2	2-1/4			■			■		
400, 500, 1600, 2600	54°	7/16	2-1/4	(NO ADAPTER FOR THIS APPLICATION)							
<b>GREAT PLAINS</b>											
8000, 7000	47°	7/16	1-3/4		■						
<b>GYRAL IMPLEMENTS</b>											
PENETRATOR T23, T25	43°	1/2	BOTH			■	■		■	■	■
AG BNOSS T30	43°	7/16	BOTH			■	■		■	■	■
<b>GYSLER</b>											
CHISEL PLOWS	47°	7/16	2-1/4			■			■		■
<b>HESSTON</b>											
FIELD CULTIVATORS	47°	1/2	1-3/4		■						
CHISEL PLOWS	50°	1/2	2-1/4			■			■		
<b>HINIKER</b>											
FIELD CULTIVATORS	47°	7/16	1-3/4		■						
CHISEL PLOWS	50°	1/2	2-1/4			■			■		
<b>HORWOOD BAGSHAW</b>											
350 SCARIBAR EDGE-ON	47°	1/2	1-3/4	■							
<b>HORWARD</b>											
CHISEL PLOWS <sup>2</sup>	50°	9/16	2-1/4			■			■		
<b>INTERNATIONAL</b>											
45, 46, 47	47°	7/16	1-3/4		■						
10, 50, 55, 75, 509, 645	43°	1/2	2-1/4			■			■		■

NOTES: 200 Series adapters should not be used on a chisel plow or heavy duty cultivator unless being used for seeding. <sup>1</sup> Sweeps will not work with this combination, for knife openers only.

<sup>2</sup> Bolt sizes will require adapting.

# SPEED-LOC™ ADAPTER CHART

MAKE & MODEL	SHANK DEGREE	BOLT SIZE	HOLE CENTER	200 SERIES					410 SERIES				
				200-QCA-4700	200-QCA-4710	200-QCA-5000	200-QCA-5010	100-WDG-0700	410-QCA-5000	410-QCA-5010	410-QCA-5080	400-WDG-0300	400-WDG-0700
<b>JANKE</b>													
UNIV DIRECT DRILL	50°	1/2	2-1/4										
U/D DRILL (HYD) EARLY	50°	1/2	2-1/4										
<b>JEOFFROY</b>													
450	47°	3/8	1-3/4										
<b>JOHN DEERE<sup>2</sup></b>													
1000, 1010, 1050	43°	3/8	1-5/8	(NO ADAPTER FOR THIS APPLICATION)									
726, 2200, 2210, 2230	47°	7/16	1-3/4										
940, 960, 985	47°	7/16	1-3/4										
730	47°	7/16	1-3/4										
735, 737, 610, 655, 680, 685, 1600, 1610, 1650	50°	1/2 <sup>5</sup>	2-1/4										
1810, 1820, 1830, 1835 WITH 350 LB TRIPS	47°	1/2	1-3/4										
1810, 1820, 1830, 1835 WITH 500 LB TRIPS	50°	1/2 <sup>5</sup>	2-1/4										
2400, 2410, 2430	50°	1/2 <sup>5</sup>	2-1/4										
<b>JOHN SHEARER</b>													
UNIVERSAL CULTIVATOR	47°	7/16	1-3/4										
CHISEL PLOWS	50°	1/2	2-1/4										
<b>KONGSKILDE</b>													
C-SHANK	47°	1/2	1-3/4										
S-TINE	47°	7/16	1-5/8										
<b>KRAUSE</b>													
600, 900, 3100, 4200	47°	7/16	1-3/4										
4000	50°	1/2	2-1/4										
5630, 5635	47°	1/2	1-3/4										
<b>LEON</b>													
CP77	43°	7/16	2-1/4										
ALL OTHER LEON CHISEL PLOWS	50°	1/2	2-1/4										
FIELD CULTIVATORS	47°	7/16	1-3/4										
<b>MASSEY FERGUSON</b>													
160	47°	3/8	1-3/4										
259	47°	7/16	1-3/4										
124, 125, 126, 128, 133	54°	7/16	2-1/4	(NO ADAPTER FOR THIS APPLICATION)									
MF 7300 CHISEL PLOW	50°	1/2	2-1/4										
<b>MORRIS</b>													
L225, L233, L240, L320	47°	3/8	1-3/4										
CHALLENGER II, 9000, 9100	47°	1/2	1-3/4										
MAXIM, MAXIM II	47°	1/2	1-3/4										
MAXIM III	47°	1/2	1-3/4										
CONCEPT 2000 WITH 400 LB TRIP	47°	1/2	1-3/4										
CONCEPT 2000 WITH 550 LB TRIP	47°	1/2	1-3/4										
CONCEPT 2000 WITH LH 755 LB TRIP	50°	1/2	2-1/4										
220, 4, 5, 6, 7	43°	7/16	2-1/4										
MAGNUM I	43°	1/2	2-1/4										
912, 8900, 9000, MAGNUM II	50°	1/2	2-1/4										
MAGNUM III WITH LH 755 LB TRIP	50°	1/2	2-1/4										
<b>EDGE-ON (CONTOUR DRILL)</b>													
(NO ADAPTER FOR THIS APPLICATION)													
CHALLENGER L2480	47°	3/8	1-3/4										
<b>NEW HOLLAND</b>													
SD 440A, SD 550A AIR HOE DRILL (DEPENDENT ON SHANK OPTION)	47°	1/2	1-3/4										
SD 440A, SD 550A AIR HOE DRILL (DEPENDENT ON SHANK OPTION)	50°	1/2	2-1/4										

MAKE & MODEL	SHANK DEGREE	BOLT SIZE	HOLE CENTER	200 SERIES					410 SERIES				
				200-QCA-4700	200-QCA-4710	200-QCA-5000	200-QCA-5010	100-WDG-0700	410-QCA-5000	410-QCA-5010	410-QCA-5080	400-WDG-0300	400-WDG-0700
ST 540 CHISEL PLOW	50°	1/2	2-1/4										
ST 250	47°	1/2	1-3/4										
ST 830 WITH 350 LB TRIP	47°	1/2	1-3/4										
ST 830 WITH 550 LB TRIP (DEPENDENT ON SHANK OPTION)	47°	1/2	1-3/4										
ST 830 WITH 550 LB TRIP (DEPENDENT ON SHANK OPTION)	50°	1/2	2-1/4										
ST 830 WITH 650 LB TRIP	50°	1/2	2-1/4										
P2050, P2060 AIR HOE DRILL 350 LB OR 550 LB TRIP	50°	1/2	2-1/4										
<b>NOBLE</b>													
XR20	50°	7/16	2-1/4										
8000, 4000 MULTI-TOOL	50°	1/2	2-1/4										
<b>QUINSTAR</b>													
FIELD FINISHER	47°	7/16	1-3/4										
FALLOW MASTER III	50°	1/2	2-1/4										
<b>RYAN (RFM)</b>													
1000 SERIES	47°	7/16	1-3/4										
<b>SALFORD</b>													
FIELD CULTIVATOR	47°	7/16	1-3/4										
<b>SCHULTE</b>													
1000 SERIES	50°	7/16	2-1/4										
<b>SMALE</b>													
MULTIVATOR	47°	7/16	1-3/4										
CHISEL PLOWS	50°	1/2	2-1/4										
<b>SUMMERS</b>													
SUPERCHISEL	50°	1/2	2-1/4										
<b>SUNFLOWER</b>													
CHISEL PLOWS	50°	1/2	2-1/4										
5000, 6000, 7000	47°	7/16	1-3/4										
<b>TAYLOR</b>													
FIELD CULTIVATORS	47°	3/8	1-3/4										
<b>UNVERFERTH</b>													
PERFECTA II FIELD CULTIVATORS	47°	7/16	1-3/4										
<b>VERSATILE</b>													
DH730, DH750 WITH 350 LB & 550 LB TRIPS	47°	1/2	1-3/4										
C500 WITH 350 LB & 550 LB TRIPS	47°	1/2	1-3/4										
C600 WITH 350 LB & 550 LB TRIPS	47°	1/2	1-3/4										
C600 WITH 600 LB TRIP	50°	1/2	2-1/4										
C700 WITH 650 LB TRIP	50°	1/2	2-1/4										
<b>VICTORY</b>													
CHISEL PLOWS	50°	1/2	2-1/4										
<b>WIL-RICH</b>													
FIELD CULTIVATORS	47°	7/16	1-3/4										
CHISEL PLOWS (1993 & OLDER)	43°	7/16	2-1/4										
CHISEL PLOWS (1994 & NEWER)	50°	1/2	2-1/4										
XL2, QX2	47°	7/16	1-3/4										
<b>YEOMANS GRAHAM HOEMES</b>													
US CHISEL PLOWS	50°	1/2	2-1/4										

NOTES: <sup>2</sup> 880-BSH-2000 should be used with all split John Deere shanks. <sup>4</sup> Use wedge 880-WDG-0300 to correct pitch. <sup>5</sup> Shanks that are mounted with a vertical bolt (28" standard). <sup>6</sup> Shanks that are mounted with a horizontal bolt (28" and 32" standard).